

Amigo Running Very Slow at Full Throttle Troubleshooting Guide

You may have a mismatched throttle enclosure and motor controller. To ensure you have a compatible combination, please find the Amigo part number on the controller and on the throttle enclosure. See photos below for reference.



After you have located the two part numbers, please contact the Amigo service department at (800) 248-9131, and a technician will quickly determine if your parts are compatible.

